Approved For Release 2001/03/01: CIA-RDP33-024154000300290095-2

SECRET

DPD-3174-59

11 May 1959

MEMORANDUM FOR: Acting Chief, DPD

SUBJECT

: Malfunction Report, Period Ending 30 April 1959

1. The following malfunction information is presented for the period ending 30 April 1959:

## I. Air Frame and Engines

A. Regulator valve, Part Number SP-106380-1 failed in closed position, thus stopping all air supply to refrigerator and cockpit. Valve replaced with new valve and refrigerator and cockpit pressure normal on test flight.

## II. Communications

A. Detachment B - No malfunction report was received for April 1959. A request for the report has been made.

25X1A

Detachment C - Mission CT-59-34. 2 April The power test flight for supply fuse blew in believed that the fuse used is underrated. The fuse was replaced with a Slow-Blow fuse of same value. No further trouble was experienced.

25X1A

25X1A

Mission CT-59-38. 22 April test flight amplifier failed. The cause of the failure was poor soldering on the connection opening. The part was resoldered, causing no further difficulty.

C. There were no failures at Detachment D during April 1959.

## Approved For Release 2001/03/01 SCIPPEDP33-02415A000300290095-2

DPD-3174-59 PAGE TWO

## III. Photographic Equipment Malfunctions

- A. During the period of 1 April 1959 through 30 April 1959, there were a total of forty (40) missions reported flown using photographic equipment. Equipment malfunctioned on eight (8) of these missions giving an overall effectiveness of 80%.
- B. Equipment reliability for the above referenced period was:

	A-1 Conf.	A-2 Conf.	B. Conf.	Trackers
Missions flown	0	0	11	40
Malfunctions	0	0	3 .	, 6 ,
Per Cent Eff.	0	0	72.7%	85%

25X1A

Chief, Materiel Branch DPD-DD/P

MB/DPD-DD/P:CFW:ms

Dist: 0 & 1 - A/CH/DPD

1 - DD/P

1 - OPS/DPD

1 - MAT/DPD

1 - RI/DPD